

**ERRATA SHEET  
FOR  
MODEL PA4000 INSTALLATION, OPERATION, AND SERVICE INSTRUCTIONS**

**CAUTION**

Installation of the Park-Siren Deactivator feature will cause damage to the starter motor and related components on 1998 and later Ford vehicles. Do not connect the Park-Siren Deactivator feature to 1998 and later Ford vehicles.

When installing the Model PA4000 siren in 1998 and later Ford vehicles, disregard the instructions covering the installation of the Park-Siren Deactivator feature (Section III, Paragraph 3-5.B.3.). If the Park-Siren Deactivator feature is required, order the FS/Unitrol Park-Siren Deactivator Module (Model UPKM-1) from the factory at 708-534-4879.