



SignalMaster™ Halogen product line to be discontinued



In a continued effort to streamline our product line, the below SignalMaster™ Halogen models are now being discontinued due to sourcing issues:

DISCONTINUED MODELS

Model #	Description
320142	20", (4) lamp, 30-ft cable
320162	31", (6) lamp, 15-ft cable
320172	42", (8) lamp, 15-ft cable
320182	42", (8) lamp, 30-ft cable
320192	42", (8) lamp, 50-ft cable
320612	31", (6) lamp, 30-ft cable
321102	42", (8) lamp, 15-ft cable
330302	(1) 320612 and (1) 331105-SB* controller
322112	(1) 320182 light and (1) 331105-SB* controller
322132	(1) 320182 light, (1) 331105-SB* controller and (1) 320320* mount

* The 331105-SB SignalMaster Controller and 320320 are still available



MU832 | 6-1-2020

RECOMMENDED SUBSTITUTE

Latitude™ SignalMaster™

- LED directional warning stick light
- Available in 6-head or 8-head models
- Three LEDs per position
- Interior and exterior mounting brackets are available; compatible with Federal Signal's SignalMaster brackets
- Innovative co-extrusion, polycarbonate housing provides moisture resistance
- Solaris® LED reflector technology
- ROC (Reliable Onboard Circuitry)™ technology
- Each model includes left, right and center-out warning signals
- Five-year warranty

TIMING

New orders for these models will no longer be accepted after August 1, 2020. Any inventory still in stock after that date will be available only "while supplies last".

For more information, please contact your local Federal signal sales representative or visit our website at www.fedsig.com