



SignalMaster models of the Cuda TriOptic product line to be discontinued



Federal Signal will be discontinuing its Cuda SignalMaster line of directional warning lights. All model numbers starting with the following 6-digits will be discontinued:

328000	328002	328010	328181
328001	328003	328180	328800
328801			

Timing

New orders for these models will no longer be accepted after March 31, 2011. Any new orders received must be for shipment prior to April 30, 2011.

Recommended Alternative

Federal Signal's new VPX SignalMaster line of LED directional warning lights is a suitable alternative to the models being discontinued. Following is a cross-reference showing the recommended substitute for several popular configurations:

Obsolete Models	Substitute Models	Description
328001F	320852	VPX SignalMaster, LED, (A-A-A-A-A-A) 6-head, 31-inch, 15-ft cable
328001F-30	320862	VPX SignalMaster, LED, (A-A-A-A-A-A) 6-head, 31-inch, 30-ft cable
328180F	320872	VPX SignalMaster, LED, (A-A-A-A-A-A-A-A) 8-head, 42-inch, 15-ft cable
328180F-30	320882	VPX SignalMaster, LED, (A-A-A-A-A-A-A-A) 8-head, 42-inch, 30-ft cable

For more information, please visit our website at www.fedsig.com or contact us at 1-800-682-8022.