



Obsolescence of Bracket Kits for Cuda TriOptic

Federal Signal will be discontinuing several bracket models that have been used with Cuda TriOptic warning lights. This change affects the Federal Signal models listed below.

PART NUMBER	DESCRIPTION
350201	MIRROR MOUNT KIT,CudaTri
350201-01	MIRROR MNT,CROWN VIC,
350201-02	HEADLINER MNT KIT,CV
350201-04	REAR HEADLINER MNT,TRIOPT
350201-06	CHILD HOOK BKT KIT,TRIOPT
350201-07	KIT,OFFSET,MTG BKT
350201-08	KIT,OFFSET,MTG BKT,
350202	MIRROR MOUNT,IMPALA,Cuda
350202-01	MNT KIT,IMP HDLINER,TRIOPT
350203	SUCTION CUP MOUNT,CudaTri
350204	MIRROR MOUNT,INTREPID,
350204-01	SIDE MIRROR MNT KIT,CROWN
350204-02	SIDE MIRROR MNT,KIT,IMPAL
350205	KIT,MTG.,SWIVEL,3.5
350207	KIT,MTG.,SWIVEL,5
350207-01	MTG. KIT, CUDA SGMSTR
350209	CNTR HEADLINER, MNT CV
350212	MTG. KIT, SUCTION CUP
350212-01	KIT,BRKTS&COVER,351016
350212-02	KIT,BRKTS&COVER,351014
350300-01	SUN VISOR, TRIOPT 6 PAK
350601	MTG KIT,SIGMASTER 328000

Timing

New orders for these models will no longer be accepted after **June 30, 2011.**

All orders must be for shipment prior to **July 31, 2011.**

For more information, please contact your local Federal Signal sales representative, visit our website at www.fedsig.com or contact us at 1-800-682-8022.