




Obsolescence of DeltaRay "323105" models



Federal Signal will be discontinuing its DeltaRay LED Visor light product line. All model numbers starting with "323105" will no longer be available.



Recommended Substitute

Federal Signal's Viper S2 interior-mount LED warning lights are a potential alternative to the DeltaRay product line.

Obsolete Models	Description	Substitute Models	Description
323105-22	DeltaRay II visor light, Amber/Amber	329000-22	Dual-head Viper S2 with cigarette plug-Amber/Amber
323105-33	DeltaRay II visor light, Blue/Blue	329000-33	Dual-head Viper S2 with cigarette plug-Blue/Blue
323105-42	DeltaRay II visor light, Red/Amber	329000-42	Dual-head Viper S2 with cigarette plug-Red/Amber
323105-43	DeltaRay II visor light, Red/Blue	329000-43	Dual-head Viper S2 with cigarette plug-Red/Blue
323105-44	DeltaRay II visor light, Red/Red	329000-44	Dual-head Viper S2 with cigarette plug-Red/Red

Timing

Model 323105-44 is obsolete effective immediately. No new orders will be accepted for this model.

The remaining models will only be available "while supplies last". There is a limited amount of inventory available on these models, and they will be sold on a "first-come-first-serve" basis until the remaining stock has been depleted.

For more information, please contact your local Federal Signal sales representative, visit our website at www.fedsig.com or contact us at 1-800-682-8022.