



Federal Signal will discontinue the IVP 100 halogen beacons



Affected Models:

All ViewPoint IVP models will be discontinued including the following:
IVP100-A, IVP100-B, IVP100-B-24, IVP100-C, IVP100-R, IVP100-R-24, and IVP100-G

Timing:

New orders for ViewPoint IVP models will not be accepted after January 1, 2014.

Suggested Alternatives:

Suggested alternatives for the ViewPoint IVP models include a variety of other Federal Signal beacons. Alternative beacons include the Vision SLR® LED beacons or Sentry® halogen beacons. Detailed product information can be found by visiting the following links:

Vision IVP SLR®

<http://www.fedsig.com/products/356/ivpvslr>



Sentry®

<http://www.fedsig.com/products/85/sentry>



*For more information, please contact your local Federal Signal representative or customer service.
Fire/EMS/Police Inquiries: 800-264-3578.*