



Viper® LC to be discontinued

In our continuing efforts to stream-line our product offering, Federal Signal is discontinuing the Viper® LC interior warning light models.



Models being discontinued	Recommended substitute model
329950-A	329001-2
329950-B	329001-3
329950-R	329001-4
329950-RR	329001-44
329950-BR	329001-34 or 329001-43
329950-BB	329001-33
329950-AA	329001-22
329950-RW	329252-RWRW
329950-RA	329001-42 or 329001-24
329950-BW	329252-BWBW

Timing

New orders for the discontinued models listed above will no longer be accepted after May 31, 2014. Any new orders received must be for shipment prior to June 30, 2014.

Recommended Substitute

The recommended substitute for the Viper LC would be the **Viper® S2** or **SpectraLux® Viper® S2** model.



For more information, please visit our website at www.fedsig.com or contact us at 1-800-264-3578.