



## Legend® LPX Serial Light Bar to be discontinued

In our continuing efforts to stream-line our product offering and improve efficiencies, Federal Signal is discontinuing the Legend LPX serial light bar.

### RECOMMENDED SUBSTITUTE

The recommended substitute for the Legend LPX serial light bar is our Legend serial light bar.



| Discontinued Models                   | Recommended Substitute                |
|---------------------------------------|---------------------------------------|
| LPX45Z / LPX45ZS                      | LGD45Z / LGD45ZS                      |
| LPX45Z-AMBR2H6 (Work Truck stock bar) | LGD45Z-AMBR2H6 (Work Truck stock bar) |
| LPX53Z / LPX53ZS                      | LGD53Z / LGD53ZS                      |
| LPX53Z-00025S (Work Truck stock bar)  | LGD53Z-AMBR1H6                        |
| LPX53Z-AMBR2H6 (Work Truck stock bar) | LGD53Z-AMBR2H6 (Work Truck stock bar) |
| LPX61Z / LPX61ZS                      | LGD61Z / LGD61ZS                      |
| LPX70Z / LPX70ZS                      | LGD70Z / LGD70ZS                      |
| LPX70Z-00002 (Work Truck stock bar)   | LGD70Z-00004                          |

***This change does not affect the discrete-wired Legend LPX Discrete light bar (models LPX45D, LPX53D, LPX61D or LPX70D).***

### TIMING

New orders for the discontinued Legend LPX serial light bars will no longer be accepted after December 29, 2017. (Work Truck stock bars will be accepted until the inventory has been depleted.)

For more information, contact your local Federal Signal Sales Representative or visit our website at [www.fedsig.com](http://www.fedsig.com)