

2561479 Rev. C1 0121

Warning for Ford Vehicles

NOTICE

Installation of the Park-Siren Deactivator feature will cause damage to the starter motor and related components on 1998 and later Ford vehicles. Do not connect the Park-Siren Deactivator feature to 1998 and later Ford vehicles.

When installing the Model PA4000 siren in 1998 and later Ford vehicles, disregard the instructions covering the installation of the Park-Siren Deactivator feature. If the Park-Siren Deactivator feature is required, order the FS/Unitrol Park-Siren Deactivator Module (Model UPKM-1) from Customer Support at 1-800-264-3578.