

ULTRASTAR® LED BEACON

ULTRASTAR LED BEACON TO BE DISCONTINUED.
SPIRE® BEACON IS THE RECOMMENDED SUBSTITUTE.



As part of our ongoing efforts to streamline our product offerings, we are discontinuing all UltraStar® LED beacons. We recommend replacing them with the Spire® beacon.

AFFECTED MODELS

DISCONTINUED ULTRASTAR MODEL	DESCRIPTION	RECOMMENDED SPIRE SUBSTITUTE
252650-02SC	Die-cast permanent/1-inch pipe mount, Amber dome	200SD-A
252651-02SC	Magnet mount, Amber dome	200SM-A
252657-02SC	Die-cast permanent/1-inch pipe mount, Amber dome, dust cover	200SDDC-A
447302	UltraStar® LED vibration mount kit	N/A
448330	UltraStar LED branch guard	200B-SHORT
Z8444371A	Replacement UltraStar LED aluminum base	N/A
Z8444374A-03	Replacement UltraStar LED dome, Amber	N/A
Z8444397A	UltraStar LED J-bolt mount kit	N/A

TIMING

Orders for the discontinued UltraStar® LED models, accessories, and replacement parts will be accepted while supplies last.