

CONVERGENCE NETWORK

NEW FEATURES ADDED TO THE CONVERGENCE NETWORK CONFIGURATION SOFTWARE



Version 3.5.0.1 of the Convergence Network Configuration software is available today to download. This new version replaces the current version 3.5.0.0. The following new features have been added to the software.

Firmware Update

- New Pathway™ Firmware Version (1.1.0.6)
- New Pathfinder® PF400/PF400Q Firmware Version (1.0.0.19)
- New Pathfinder® PF200 Firmware Version (3.2.0.12)

Improvements and Additions

- Resolved a visual issue in the Configuration Viewer where “Tone Off” was not correctly displayed for Channel 1 and Channel 2
- Fixed FSJoin™ Relay Tab BCM Disconnect Label (visual bug)
- Fixed BCM Disconnect/Connect status. Did not consistently update visually on relays when toggled
- Validation implemented to prevent adding the Perimeter Breach Warning System without a supported amplifier
- Support added for the 51” VALR/INTG Passenger Board (board number 20000639)
- Visual bug fix related to Bed light feature

TIMING

Version 3.5.0.1 of the Convergence Network Configuration Software can be download today:

<https://www.fedsig.com/software-downloads>

All trademarks are property of their respective owners.