



Obsolescence of IVP200 beacons

Due to declining demand, Federal Signal is discontinuing the IVP200, halogen beacon, 175 FPM rotator with hose bed light for fire apparatus, effectively immediately.

Orders currently in the system will be honored and all future orders will be taken until limited stock runs out.



IVP200

Recommended Alternative

Federal Signal offers a IVP100, halogen 175 FPM rotator beacon. This beacon has a \$184.25 List Price for 2012.



IVP100-R

For more information, please contact your local Federal Signal sales representative, visit our website at www.fedsig.com or contact us at 1-800-682-8022.