#### 25500532 Rev. A0 0119

# Safety Message to Installers of Warning Light Equipment

## **A** WARNING

People's lives depend on your proper installation and servicing of Federal Signal products. It is important to read and follow all instructions shipped with this product and the original product. In addition, listed below are some other important safety instructions and precautions you should follow:

- To properly install the lighting and siren systems, you must have a good understanding of automotive systems, along with proficiency in the installation and use of safety warning equipment.
- Do not install equipment or route wiring in the deployment path of an airbag.
- If a vehicle seat is temporarily removed, verify with the vehicle manufacturer if the seat needs to be recalibrated for proper airbag deployment.
- You should frequently inspect the light system to ensure that it is operating properly and that it is securely attached to the vehicle.
- When drilling into a vehicle structure, be sure that both sides of the surface are clear of anything that could be damaged.
- Refer to the instructions packed with related products for additional precautions and information.
- Do not stare directly into the lights at a close range or permanent damage to your eyesight may occur.
- All effective sirens and horns produce loud sounds (120 dB) that may cause permanent hearing loss. Always minimize your exposure to siren sound and wear hearing protection. Do not sound the siren indoors or in enclosed areas where you and others will be exposed to the sound.
- File these instructions in a safe place and refer to them when maintaining and/or reinstalling the product.

Failure to follow all safety precautions and instructions may result in property damage, serious injury, or death.

# Introduction

This publication has instructions for using the Bracket Kit to mount dual ES100C speakers in the lower grille of the 2015 Dodge Charger.

# **Unpacking the Kit**

After unpacking the kit, inspect it for damage that may have occurred in transit. If it has been damaged, do not attempt to install or operate it. File a claim immediately with the carrier, stating the extent of damage. Carefully check all envelopes, shipping labels, and tags before removing or destroying them. Ensure that the parts in the KIT CONTENTS LIST are included in the package. Disposal of all shipping materials must be carried out in accordance with national and local codes and standards. If you are missing any parts, contact Customer Support at 1-800-264-3578, 7 a.m. to 5 p.m., Monday through Friday (CT).

Qty.	Description	Part Number
1	BRKT, DUAL ES100C, CHGR	856702787
2	WASH, FLT, SS, .344 X 3/4 X .050	7072A031
6	BOLT, CAP, 5/16-18, HEX, SS, 18-8 SS	7002A005-14
2	NUT, HEX DBL CHAM SS 5/16-18	7057A027
4	LKWASH, SPLIT 5/16 SCR SS	7074A020

#### Table 1 Kit contents

## **Installing the Brackets**

#### A WARNING

AIRBAG DEPLOYMENT: Do not install equipment or route wiring in the deployment path of an airbag. Failure to observe this warning will reduce the effectiveness of the airbag or potentially dislodge the equipment, causing serious injury or death.

## NOTICE

DRILLING PRECAUTION: When drilling holes, check the area you are drilling into to be sure you do not damage vehicle components. All drilled holes should be deburred and all sharp edges should be smoothed. All wire routings going through drilled holes should be protected by a grommet or convolute/split loom tubing.

**IMPORTANT:** Plan all cable routing before the installation.

- 1. To access the area behind the grille, remove the fascia per the manufacturer's service manual.
- 2. Position the center of the bracket in the center of the bumper. The bracket should be backwards so that the mounting holes are touching the bumper. Mark the two mounting holes.
- 3. Drill the 2 holes with a 0.332" drill bit.
- 4. Mount the speakers to the bracket with the 5/16" bolts and lock washers.
- 5. Install the bracket to the bumper with the 5/16" bolts and flat washers. See Figures 1 & 2.

Figure 1 ESB2-CHGR15 bracket kit installed on Dodge Charger



ESB2-CHGR15 Bracket Kit for the 2015 Dodge Charger




Figure 2 Exploded view of ESB2-CHGR15 bracket kit installed on Dodge Charger

6. Complete the installation according to the instructions provided with the speaker.

#### **A** WARNING

SOUND HAZARD: All effective sirens and horns produce loud sounds (120 dB) that may cause permanent hearing loss. Always minimize your exposure to siren sound and wear hearing protection. Do not sound the siren indoors or in enclosed areas where you and others will be exposed to the sound.

#### 

# HOT SURFACE: The speaker gets hot enough to burn you. Always allow it to cool before handling it.

- 7. Test the siren for proper operation.
- 8. Reassemble the vehicle according to the manufacturer's service manual.

# **Getting Technical Support**

For technical support, please contact:

Federal Signal Corporation Service Department Phone: 1-800-433-9132 Fax: 1-800-343-9706 Email: empserviceinfo@fedsig.com

# **Getting Repair Service**

The Federal Signal factory provides technical assistance with any problems that cannot be handled locally. Any units returned to Federal Signal for service, inspection, or repair must be accompanied by a Return Material Authorization (RMA). Obtain a RMA from a local Distributor or Manufacturer's Representative. Provide a brief explanation of the service requested, or the nature of the malfunction.

Address all communications and shipments to the following:

Federal Signal Corporation Service Department 2645 Federal Signal Dr. University Park, IL 60484-3167

# **Ordering Replacement Parts**

To order replacement parts, call Customer Support at 1-800-264-3578, 7 a.m. to 5 p.m., Monday through Friday (CT) or contact your nearest distributor.

Dodge is a registered trademark of FCA US LLC.