



Obsolescence of Ricochet Strobe Power Supply and Related Kits

Due to declining demand, Federal Signal is discontinuing the Ricochet series of strobe power supplies and related systems. A selection of service parts for the Ricochet family will still be available to accommodate the current user base. The models below are being discontinued.



Part #	Description
413106	Ricochet 6-head Strobe Power Supply
413120B	Ricochet Strobe Power Supply, (4) Clear corner strobes, (2) 10' cables, (2) 22' cables
413121	Ricochet Strobe Power Supply, (4) Clear corner strobes, (2) 16' cables, (2) 30' cables
413122B	Ricochet Strobe Power Supply, (6) Clear corner strobes, (4) 10' cables, (2) 22' cables
413126B	Ricochet Strobe Power Supply, (4) Clear corner strobes, (2) 16' cables, (1) 22' cable
413127B	Ricochet Strobe Power Supply, (4) Clear corner strobes, (4) 16' cables, (1) 25' cable, (1) 30' cable

Timing

All existing orders will be fulfilled, and new orders for the Ricochet series will not be accepted after July 31, 2012. Any new orders received must be for shipment prior to September 1, 2012.

Recommended Alternatives

For customers interested in flashing Corner Strobe Systems, Federal Signal's **Silver Series** remains an alternative to the Ricochet series with many cable-length and industry-standard connector options.

Further information can be found at the following link:

http://www.fedsig.com/products/169/silver_series

Flashing Corner LED Systems are also available, including the **In-Line Corner LED (416200) Systems** and **Corner LED Systems (CLED)**. These systems use the latest generation of LEDs for bright warning and enhanced reliability.

Please see the links below for more details.

http://www.fedsig.com/products/288/in_line_corner_led

http://www.fedsig.com/products/250/corner_led

For more information, please contact your local Federal Signal sales representative, visit our website at www.fedsig.com or contact us at 1-800-682-8022.