



Model 851/Model 651 Strobe Beacons to be Discontinued



In our continuing efforts to stream-line our product offering, Federal Signal is discontinuing the Model 851 and Model 651 strobe beacons.

TIMING

Effective immediately, new orders for the Model 851 and Model 651 strobe beacons will not be accepted.

RECOMMENDED ALTERNATIVES

Suggested alternatives for the Model 851 and Model 651 strobe beacons are the Model 851 LED and Model 651 LED beacons.

Model 851 LED Beacon

Model #	Description
420450-02	Open-style bottom, Amber
420460-02	Utility light, blackout lens, clear dust cover, branch guard, polycarbonate mounting base, Amber

Model 651 LED Beacon

Model #	Description
420223-02	Open-style bottom, Amber
420222-02	Utility light, blackout lens, clear dust cover, branch guard, aluminum mounting base, Amber

For more information, please contact your local Federal Signal sales representative, visit our website at www.fedsig.com or contact Amber Customer Care at 800-824-0254.