

October 1, 2015

Dear Federal Signal Customer,

Federal Signal is announcing service parts obsolescence of **STH10** sirens that includes part number **Q-BSA** ((2)BRUSH, (4)SPRING ASSEMBLY REPLACEMENT). Products reach the end of their Product Life Cycle for a number of reasons. These reasons may be due to market demands, technology innovation and development driving changes, or the products simply mature over time and are replaced by functionally richer technology.

This letter is for Federal Signal customers worldwide, to inform them of our end of support plans.

End of Support

Federal Signal is committed to providing the highest level of customer service. Federal Signal was making diligent efforts to repair this product for more than 20 years after discontinuing it. However, we are not able to procure parts for this obsolete product line.

Below are key timelines and support options that are now available:

Date	Activity
Dec. 4 th 1995 (1-phase)	End of Sale (no longer orderable or available for purchase)
Dec. 5 th 2005 (3-phase)	
September 17 th 2015	End of Support for STH10

Upgrade Options

The Eclipse 8 siren with a DCFCB series siren controller would be a suitable replacement. Product information can be found at:

<http://www.alertnotification.net/product/eclipse8-omni-directional-siren>

<http://www.alertnotification.net/product/dcfctbd-two-way-digital-controller-batteries>

For a design consultation and questions, contact your Federal Signal representative or the Federal Signal Technical Support team:

- ✓ **Presales Support:** 1-800-524-3021 Option 2 or rfq@federalsignal.com
- ✓ **Technical Support:** 1-800-524-3021 Option 3 or techsupport@federalsignal.com

Sincerely,

Federal Signal Alerting & Notification Systems