



Speaker Assembly
Models TS-100 and TS100-RF Series A1

PPL 0050

PARTS LIST

Printed 1999

Item No.	Description	Part No.	Qty.
1	Driver, Model TS-100	Z8556C053A-01	1AR
2	Washer, Steel	Z7072A137A	1
3	Washer, Vellutex	Z8283A451	3
4	Bracket Assembly, Speaker	Z8470124C	1
5	Weather Guard Assembly (Model TS-100 only)		1AR
6	Gasket, Weather Guard (Model TS100-RF only)		1AR
7	Projector	Z8470D118	1
8	Washer, Vellutex	Z8283A453	1
9	Washer, Rubber	Z8283A452	2
10	Cone, Black (Model TS-100 only)	Z8283B500-01	1AR
11	Nameplate	Z81461562A-01	1
Not Shown			
	Screw Mtg. Driver to Bracket		1AR
	Replacement Head Hit (including coil and diaphragm)	Z8556A082B	1AR

DO NOT ORDER PARTS BY ITEM NUMBER.
Give model, description and part number.
When a part number is not supplied, the part is **NOT** available.
Refer to PARTS PRICE LIST (Part No. 1001) for prices of parts.

Federal Signal Corporation
2645 Federal Signal Drive
University Park, IL 60466

Printed in U.S.A.