

REVERSE CAMERA

REVERSE CAMERA REPLACEMENT WIRING HARNESSES TO BE DISCONTINUED



Federal Signal is discontinuing the replacement wire harnesses for Reverse Camera monitors due to low sales. The recommended option moving forward will be a new monitor.

DISCONTINUED MODELS

DISCONTINUED MODEL	DESCRIPTION
CAMADP-AHD-2-SB	Replacement wire harness, 5.6-inch monitor CAMLCD-AHD-56-SB
CAMADP-AHD-4	Replacement wire harness, 7.0-inch monitor CAMLCD-AHD-70

TIMING

Orders for replacement wire harnesses will be accepted while supplies last.